# USB DRIVER INSTALLATION - WINDOWS 7

To copy the required drivers for Windows 7 into the correct directory, you have to run the AS55X_service software explicitly as administrator <u>before</u> connecting the device via USB cable.

Therefore use the right click on the menu item and select "Run as administrator".

Finally you have to confirm the installation work, because the driver has not been verified.

Otherwise the driver will not be installed and the device is not detected by the operating system.